## 3562G

## **MUST BE FITTED BY A PROFESSIONAL**

1	e led	WALL PLATE	x1	Using the bubble level to ensure the wall plate is level, Pre-drill 3 holes with a 10mm bit to 50mm deep. Insert wall anchors into the holes, then using long bolts to mount the wall to studs. Under the direction of the arrow, Fix the levels(G) on the wall plate.
2		Aluminum assembly	<b>x</b> 1	
3	(000000	Panel connecting piece	x1	
А	(Madaaaaa)	M5.3x40mm screw	x4	2
В		WALL PLUG	x4	
С	<b>⊕</b> )⊃	M4x12mm Cross round screw	x4	
D		M5x12mm Cross round screw	x4	
E		4mm Wrench	x1	
F		6mm Wrench	x1	CHJ
G		Levels	x1	
Н		M5x12mm flat head screw	x8	
I		M5 Screw nut	x8	
J		M6x12mm Cross round screw	x4	

## **MUST BE FITTED BY A PROFESSIONAL**