3564G

MUST BE FITTED BY A PROFESSIONAL

1		WALL PLATE	x1	Using the bubble level to ensure the wall plate is level Pre-drill 3 holes with a 10mm bit to 50mm deep.	el,
2		Aluminum assembly	x 1	Insert wall anchors into the holes, then using long bolts to mount the wall to stude Under the direction of the arrow, Fix the levels (G on the wall plate.	
3	(000000	Panel connecting piece	x1		
А	<i>caaaaaaa</i> ¶	M5.3x40mm screw	x4		
В		WALL PLUG	x4	H	
С	(1)	M4x12mm Cross round screw	x4		
D	(4)	M5x12mm Cross round screw	x4		
E		4mm Wrench	x1		
F		6mm Wrench	x1	3 CDJ	
G		Levels	x1		
Н		M5x12mm flat head screw	x8		
I		M5 Screw nut	x8		
J		M6x12mm Cross round screw	x4		

MUST BE FITTED BY A PROFESSIONAL